

EPA ID: NYD981186919 Site Name: DENTON AVENUE LANDFILL

State ID: 130008

Alias Site Names: NORTH HEMPSTEAD LF (NYD980507230)

City: NEW HYDE PARK

County or Parish: NASSAU

State: NY

Refer to Report Dated: 12/01/1991

Report Type: SITE REASSESSMENT 001

Report Developed by: DEC

DECISION:

☒ 1. Further Remedial Site Assessment under CERCLA (Superfund) is not required because:

☒ 1a. Site does not qualify for further remedial site assessment under CERCLA (No Further Remedial Action Planned - NFRAP)

☐ 1b. Site may qualify for action, but is deferred to:

☐ 2. Further Assessment Needed Under CERCLA:

2a. Priority: ☐ Higher ☐ Lower

2b. Other: (recommended action) NFRAP (No Further Remedial Action Planned)

DISCUSSION/RATIONALE:

The U.S. Environmental Protection Agency (EPA) has determined that no further remedial action by the Federal Superfund program is warranted at the referenced site, at this time. The basis for the no further remedial action planned (NFRAP) determination is provided in the attached document. A NFRAP designation means that no additional remedial steps under the Federal Superfund program will be taken at the site unless new information warranting further Superfund consideration or conditions not previously known to EPA regarding the site are disclosed. In accordance with EPA's decision regarding the tracking of NFRAP sites, the referenced site may be removed from the CERCLIS database and placed in a separate archival database as a historical record if no further Superfund interest is warranted. Archived sites may be returned to the CERCLIS site inventory if new information necessitating further Superfund consideration is discovered.

The site was used as a municipal solid waste landfill from 1953 to 1974. The site consists of two landfills separated by a storm water recharge basin: a north landfill and a south landfill. Wastes reportedly disposed at both landfills included municipal refuse and raw garbage. It is unknown whether hazardous wastes have been disposed at the landfills. Two incinerators were reportedly located on the property. The majority of the waste was incinerated prior to disposal in the unlined fill area. In 1995 USEPA's consultant conducted an Extended Site Inspection (ESI). At the time of the ESI, the southern landfill was used as a recreational facility, and the northern landfill was undeveloped. Groundwater samples from several of the on-site monitoring wells contained chromium, lead, iron, and manganese at concentrations above federal drinking water standards.

Upon review of all available data, the New York State Department of Environmental Conservation (NYSDEC) concluded the following: a) All available information concerning hazardous waste disposal has failed to locate documentation of hazardous waste disposal. b) The groundwater contamination is not the result of hazardous waste disposal. In November 1991, the NYSDEC removed the site from the Registry of Inactive Hazardous Waste Disposal Sites in New York and referred the site to the New York State Solid Waste Management Program for a proper NYCRR Part 360 closure. The New York State Department of Health (NYSDOH) concurred with the NYSDEC action.

Site Decision Made by: ALEX KOSTIC

Signature: _____

*Alex Kostic**[Signature]*

Date: 06/16/2005

309874

